

This document describes the cumulative changes made to Portal since v2.7.4.

New In This Version

- Included the SNAP Core 2.7.2 firmware package

Errata

- `detectEvalBoards` in `evalBase.py` will incorrectly identify a SN132 if the SN132 is plugged into a wall wart. Only use this function if the SN132 is plugged into a PC. This function is used in the `McastCounter.py` example.

Installation Notes

- The installer will automatically remove a previous version of Portal if one is installed.

Related Documents

- SNAP Primer
- Portal Reference Manual
- SNAP Users Guide
- SNAP Reference Manual
- SNAP Firmware Release Notes